

CPSD - Water Fixtures Lead Content

School	Fixture	Water Source	ORIGINAL PPB TEST			Actions Items Taken	Labor Resources	SECOND PPB TEST		
			Tested	Results	Results - PPB			Tested	Results	Results - PPB
Amigos	1st floor - Gym staff bathroom CF-C	Secured	6/23/16	6/27/16	56	H2O secured	In-house			
Amigos	1st floor - Room 104 (High sink) CF-C	Secured	6/23/16	6/27/16	30	H2O secured	In-house	10/5/16	10/12/16	5
Amigos	1st floor - Room 106 CF-C	Secured	6/23/16	6/27/16	28	H2O secured	In-house	10/5/16		
Amigos	2nd floor - Teachers lounge men's bathroom BF-C	Secured	6/23/16	6/27/16	14	H2O secured	In-house			
Amigos	2nd floor - Library sink CF-C	Secured	6/23/16	6/27/16	13	H2O secured	In-house			
Amigos	3rd floor - Room 306 Entrance Wall Sink CF-C	Secured	6/23/16	6/27/16	13	H2O secured	In-house			
Amigos	3rd floor - Room 306 Clock wall sink CF-C	Secured	6/23/16	6/27/16	12	H2O secured	In-house			
Baldwin	Basement kitchen sink middle KC	Secured	7/8/16	7/12/16	49	H2O secured	Contracted	9/13/16	9/15/16	ND
Baldwin	Basement kitchen left sink KC	Secured	7/8/16	7/12/16	25	H2O secured	Contracted	9/13/16	9/15/16	2
Baldwin	2nd floor - Room 215 bubbler DW	Secured	7/8/16	7/12/16	15	H2O secured	Contracted	9/13/16	9/15/16	9
Baldwin	2nd floor - Room 204 bubbler DW	Secured	7/8/16	7/12/16	13	H2O secured	Contracted	9/13/16	9/15/16	ND

10/6 - Will place "Non-Potable Water Source - Do Not Drink" signage

10/6 - Will place "Non-Potable Water Source - Do Not Drink" signage
 10/6 - Will place "Non-Potable Water Source - Do Not Drink" signage
 9/2 - Placed "Non-Potable Water Source - Do Not Drink" signage
 9/2 - Placed "Non-Potable Water Source - Do Not Drink" signage

School	Fixture	Water Source	Tested	Results	Results - PPB	Actions	Labor	ADDITIONAL PPB TEST			ADDITIONAL PPB TEST					
								Tested	Results	Results - PPB	Tested	Results	Results - PPB			
CPORT	Basement room L-6 bubbler DW	Secured	6/3/16	6/8/16	15	Fixture replaced	In-house	7/8/16	7/12/16	35	7/19/16	7/25/16	27,18,15	8/18/16	8/22/16	9, 8
CPORT	2nd floor - Room 100 CF-C	Secured	6/3/16	6/8/16	43	Fixture replaced	In-house	7/8/16	7/12/16	166	7/19/16	7/25/16	145,81,18	8/18/16	8/22/16	2, 1
CPORT	3rd floor - Gym girls bathroom BF-C right	Secured	6/3/16	6/8/16	11	Fixture replaced	In-house	7/8/16	7/12/16	NA	7/19/16	7/25/16	NA	8/18/16		
CPORT	4th floor - Room 202 CF-C	Secured	6/3/16	6/8/16	19	Fixture replaced	In-house	7/8/16	7/12/16	36	7/19/16	7/25/16	127,80,18	8/18/16	8/22/16	2, 1
CPORT	4th floor - Room 204 CF-C	Secured	6/3/16	6/8/16	18	Fixture replaced	In-house	7/8/16	7/12/16	24	7/19/16	7/25/16	38,12,7	8/18/16	8/22/16	1, 1
CPORT	4th floor - Room 200 CF-C	Secured	6/3/16	6/8/16	16	Fixture replaced	In-house	7/8/16	7/12/16	37	7/19/16	7/25/16	17,16,19	8/18/16	8/22/16	1, 1
CPORT	RISER #1 - Sample 1	Secured	7/22/16	7/25/16	4	***** In-house plumbers replacing riser and distribution piping to identified rooms.										
CPORT	RISER #1 - Sample 2	Secured	7/22/16	7/25/16	1											

ADDITIONAL PPB TEST		
Test to determine if lead issue is found in the riser piping.		
Tested	Results	Results - PPB
7/19/16	7/25/16	27,18,15
7/19/16	7/25/16	145,81,18
7/19/16	7/25/16	NA
7/19/16	7/25/16	127,80,18
7/19/16	7/25/16	38,12,7
7/19/16	7/25/16	17,16,19

ADDITIONAL PPB TEST		
New risers installation completed on 8/17/16.		
Tested	Results	Results - PPB
8/18/16	8/22/16	9, 8
8/18/16	8/22/16	2, 1
8/18/16		
8/18/16	8/22/16	2, 1
8/18/16	8/22/16	1, 1
8/18/16	8/22/16	1, 1

FMA	Basement - Room 007 BF	Secured	5/26/16	5/31/16	53	H2O secured	Contracted	9/2/16	9/8/2016	ND
FMA	Room 103 - High CF	Secured	5/26/16	6/1/16	14	H2O secured	Contracted	9/2/16	9/8/2016	ND
FMA	Room 205 CF	Secured	5/26/16	6/1/16	13	H2O secured	Contracted	9/2/16	9/8/2016	1
FMA	Room 209 CF	Secured	5/26/16	6/1/16	11	H2O secured	Contracted	9/2/16	9/8/2016	1
FMA	Room 301 Lab sink used for drinking water CF	Secured	5/26/16	6/1/16	11	H2O secured	Contracted	9/2/16	9/8/2016	
G&P	1st floor - Room 111 BF-C (Girl's room)	Secured	6/24/16	6/28/16	1151	H2O secured	Contracted	9/2/16	9/8/2016	3
G&P	1st floor - Room 101 BF-C	Secured	6/24/16	6/28/16	444	H2O secured	Contracted	9/2/16	9/8/2016	12
G&P	1st floor - Gym sink (Sue) CF-C	Secured	6/24/16	6/28/16	28	H2O secured	Contracted	9/2/16	9/8/2016	63
G&P	1st floor - Room 116 CF-C	Secured	6/24/16	6/28/16	27	H2O secured	Contracted	9/2/16	9/8/2016	4
G&P	1st floor - Gym sink (Jay) CF-C	Secured	6/24/16	6/28/16	21	H2O secured	Contracted	9/2/16	9/8/2016	3
G&P	1st floor - Room 110 CF-C	Secured	6/24/16	6/28/16	21	H2O secured	Contracted	9/2/16	9/8/2016	2
G&P	2nd floor - Bathroom far right sink BF-C	Secured	6/24/16	6/28/16	21	H2O secured	Contracted	9/2/16	9/8/2016	22
G&P	2nd floor - Library sink CF-C	Secured	6/24/16	6/28/16	19	H2O secured	Contracted	9/2/16	9/8/2016	17
G&P	2nd floor - Room 212 CF-C	Secured	6/24/16	6/28/16	12	H2O secured	Contracted	9/2/16	9/8/2016	5

9/2 - Placed "Non-Potable Water Source - Do Not Drink" signage

9/13/16 - Take fixture off line.

9/13/16 - Take fixture off line.

9/13/16 - Take fixture off line.

Haggerty	ALL RESULTS WITHIN LEVELS	NA	6/2/16	6/9/16	WITHIN LIMITS					
King Open(359B)	Basement - Art room low sink CF-C	Secured	6/16/16	6/20/16	17	Fixture replaced	In-house	7/22/16	7/27/16	6
King Open(359B)	Basement - Room K3 high sink CF-C	Secured	6/16/16	6/20/16	16	Fixture replaced	In-house	7/22/16	7/27/16	7
King Open(359B)	Basement - Inner staff bathroom BF-C	Secured	6/16/16	6/20/16	11	Fixture replaced	In-house			21
King Open(359B)	Basement - Room K3 low sink CF-C	Secured	7/8/16	7/15/16	2853	Fixture replaced	In-house			
King Open(359B)	Kitchen - Small sink KC	Secured	6/16/16	6/20/16	819	Fixture replaced	In-house	7/22/16	7/27/16	381
King Open(359B)	Kitchen - Small sink KH	Secured	6/16/16	6/20/16	31	Fixture replaced	In-house	7/22/16	7/27/16	340
King Open(359B)	Kitchen BF-C	Secured	6/16/16	6/20/16	17	Fixture replaced	In-house	7/22/16	7/27/16	10
King Open(359B)	1st floor - Room 125 CF-C	Secured	6/16/16	6/20/16	20	NA	In-house	RM 125 SCIENCE ROOM - BACKFLOW		
King Open(359B)	1st floor - Room 109 CF-C	Secured	6/16/16	6/20/16	19	Fixture replaced	In-house	7/22/16	7/27/16	10
King Open(359B)	2nd floor - Room 219 CF-C	Secured	6/16/16	6/20/16	216	NA	In-house	RM219 SCIENCE ROOM - BACKFLOW		

ADDITIONAL PPB TEST		
Tested	Results	Results - PPB
10/5/16	10/12/16	1
10/5/16	10/12/16	1

8/22 - Confirmed (Small hand washing sink only)
 8/22 - Confirmed (Small hand washing sink only)

9/2 - Placed "Non-Potable Water Source - Do Not Drink" signage

9/2 - Placed "Non-Potable Water Source - Do Not Drink" signage

CPSD - Water Fixtures Lead Content

King Open(359B)	2nd floor - Room L223 Sink 1 CF-C	Secured	6/16/16	6/20/16	46	Fixture replaced NA	In-house In-house	8/2/16	8/9/16	25
King Open(359B)	2nd floor - Staff bathroom BF-C	Secured	6/16/16	6/20/16	36	Fixture replaced	In-house	7/22/16	7/27/16	23

9/2 - Placed "Non-Potable Water Source - Do Not Drink" signage
9/2 - Placed "Non-Potable Water Source - Do Not Drink" signage

School	Fixture	Water Source	ORIGINAL PPB TEST			Actions Items Taken	Labor Resources	SECOND PPB TEST		
			Tested	Results	Results - PPB			Tested	Results	Results - PPB
KLF	1st floor - Nurse hall sink BF-C	Secured	6/17/16	6/21/16		H2O secured - Sink not in use. Will remove.				
KLF	1st floor - Room 101 bubbler DW	Secured	6/17/16	6/21/16	21	Fixture replaced	In-house	8/11/16	8/18/16	3
KLF	1st floor - Room 109 bubbler DW	Secured	6/17/16	6/21/16	12	Fixture replaced	In-house	8/11/16	8/18/16	4
KLF	1st floor - Room 104 bubbler DW	Secured	6/17/16	6/21/16	10	Fixture replaced	In-house	8/11/16	8/18/16	3
KLF	2nd floor - Room 201 bubbler DW	Secured	7/22/16	7/25/16	15	Fixture replaced	In-house	8/11/16	8/18/16	8
KLF	2nd floor - Room 207 bubbler DW	Secured	7/22/16	7/25/16	22	Fixture replaced	In-house	8/11/16	8/18/16	3
KLF	2nd floor - Room 208 bubbler DW	Secured	7/22/16	7/25/16	12	Fixture replaced	In-house	8/11/16	8/18/16	3
KLF	2nd floor - Room 209 bubbler DW	Secured	7/22/16	7/25/16	12	Fixture replaced	In-house	8/11/16	8/18/16	3
KLF	2nd floor - Room 202 bubbler DW	Secured	6/17/16	6/21/16	25	Fixture replaced	In-house	8/2/16	8/9/16	10
KLF	2nd floor - Room 213 bubbler DW	Secured	6/17/16	6/21/16	19	Fixture replaced	In-house	8/2/16	8/9/16	4
KLF	2nd floor - Room 212 CF-C	Secured	6/17/16	6/21/16	18	Fixture replaced	In-house	8/2/16	8/9/16	4
KLF	2nd floor - Room 210 bubbler DW	Secured	6/17/16	6/21/16	18	Fixture replaced	In-house	8/2/16	8/9/16	4
KLF	2nd floor - Room 203 CF-C	Secured	6/17/16	6/21/16	17	Fixture replaced	In-house	8/2/16	8/9/16	4
KLF	2nd floor - Room 214 back hall CF-C	Secured	6/17/16	6/21/16	17	Fixture replaced	In-house	8/11/16	SCIENCE ROOM	
KLF	2nd floor - Room 206 CF-C	Secured	6/17/16	6/21/16	17	Fixture replaced	In-house	8/2/16	8/9/16	6
KLF	2nd floor - Room 211 CF-C	Secured	6/17/16	6/21/16	17	Fixture replaced	In-house	8/2/16	8/9/16	1
KLF	2nd floor - Room 205 bubbler DW	Secured	6/17/16	6/21/16	15	Fixture replaced	In-house	8/2/16	8/9/16	8
KLF	2nd floor - Room 211 bubbler DW	Secured	6/17/16	6/21/16	12	Fixture replaced	In-house	8/2/16	8/9/16	53
KLF	3rd floor - Room 304 bubbler DW	Secured	6/17/16	6/21/16	11	Fixture replaced	In-house	8/2/16	8/9/16	4
KLF	3rd floor - Room 303 bubbler DW	Secured	6/17/16	6/21/16	10	Fixture replaced	In-house	8/2/16	8/9/16	4
KLF	3rd floor - Main office CF-C	Secured	6/17/16	6/21/16	26	Fixture replaced	In-house	8/2/16	8/9/16	4
KLF	3rd floor - Room 302 bubbler DW	Secured	6/17/16	6/21/16	20	Fixture replaced	In-house	8/2/16	8/9/16	6
KLF	3rd floor - Main office bubbler DW	Secured	6/17/16	6/21/16	20	Fixture replaced	In-house	8/2/16	8/9/16	4
KLF	3rd floor - Room 315 bubbler DW	Secured	6/17/16	6/21/16	17	Fixture replaced	In-house	8/2/16	8/9/16	83
KLF	3rd floor - Room 312 bubbler DW	Secured	6/17/16	6/21/16	16	Fixture replaced	In-house	8/2/16	8/9/16	3
KLF	3rd floor - Room 305 bubbler DW	Secured	6/17/16	6/21/16	15	Fixture replaced	In-house	8/2/16	8/9/16	15
KLF	3rd floor - Room 307 bubbler DW	Secured	6/17/16	6/21/16	14	Fixture replaced	In-house	8/2/16	8/9/16	11
KLF	3rd floor - Room 316 bubbler DW	Secured	6/17/16	6/21/16	14	Fixture replaced	In-house	8/2/16	8/9/16	14
KLF	3rd floor - Room 311 bubbler DW	Secured	6/17/16	6/21/16	14	Fixture replaced	In-house	8/2/16	8/9/16	12
KLF	3rd floor - Room 309 CF-C	Secured	6/17/16	6/21/16	13	Fixture replaced	In-house	8/11/16	8/18/16	3

ADDITIONAL PPB TEST		
Test to determine if lead issue is found in the riser piping.		
Tested	Results	Results - PPB
8/11/16	8/18/16	19, 7, 7
8/11/16	8/18/16	75, 102, 65
8/11/16	8/18/16	12, 6, 4

ADDITIONAL PPB TEST		
Tested	Results	Results - PPB
9/2/16	9/8/16	7
8/22 - Take fixture off line.		

Morse	Room E3 DW	Secured	6/2/16	6/7/16	15	H2O secured	In-house	10/5/16	10/12/16	ND
-------	------------	---------	--------	--------	----	-------------	----------	---------	----------	----

Peabody	ALL RESULTS WITHIN LEVELS	NA	6/10/16	6/14/16	WITHIN LIMITS					
---------	---------------------------	----	---------	---------	---------------	--	--	--	--	--

Tobin	2nd floor - Room 344 bubbler DW	Secured	7/7/16	7/12/16	30	H2O secured	In-house	9/2/16	9/8/2016	5
Tobin	1st floor - Room 279 bathroom sink BF-C	Secured	7/7/16	7/12/16	28	H2O secured	In-house	9/2/16	9/8/2016	3
Tobin	2nd floor - Room 339 bubbler DW	Secured	7/7/16	7/12/16	25	H2O secured	In-house	9/2/16	9/8/2016	15
Tobin	2nd floor - Room 308 bubbler DW	Secured	7/7/16	7/12/16	20	H2O secured	In-house	9/2/16	9/8/2016	3
Tobin	1st floor - Room 279 left sink CF-C	Secured	7/7/16	7/12/16	19	H2O secured	In-house	9/2/16	9/8/2016	1
Tobin	1st floor - Room 239 CF-C	Secured	7/7/16	7/12/16	17	H2O secured	In-house	9/2/16	9/8/2016	1
Tobin	2nd floor - Room 343 CF-C	Secured	7/7/16	7/12/16	16	H2O secured	In-house	9/2/16	9/8/2016	1
Tobin	1st floor - Room 290 bathroom sink BF-C	Secured	7/7/16	7/12/16	16	H2O secured	In-house	9/2/16	9/8/2016	3
Tobin	Basement - Kitchen sink large corner BF-C	Secured	7/7/16	7/12/16	15	H2O secured	In-house	9/2/16	9/8/2016	ND
Tobin	1st floor - Room 283/284 bathroom sink BF-C	Secured	7/7/16	7/12/16	13	H2O secured	In-house	9/2/16	9/8/2016	3
Tobin	1st floor - Room 204 bathroom BF-C	Secured	7/7/16	7/12/16	13	H2O secured	In-house	9/2/16	9/8/2016	1
Tobin	2nd floor - Room 342 CF-C	Secured	7/7/16	7/12/16	12	H2O secured	In-house	9/2/16	9/8/2016	2
Tobin	2nd floor - Room 340 CF-C	Secured	7/7/16	7/12/16	12	H2O secured	In-house	9/2/16	9/8/2016	1
Tobin	1st floor - Room 216 CF-C	Secured	7/7/16	7/12/16	12	H2O secured	In-house	9/2/16	9/8/2016	2
Tobin	2nd floor - Room 305 bubbler DW	Secured	7/7/16	7/12/16	22	H2O secured	In-house	9/2/16	9/8/2016	4
Tobin	2nd floor - Room 306 bubbler DW	Secured	7/7/16	7/12/16	11	H2O secured	In-house	9/2/16	9/8/2016	6

9/13/16 - Take fixture off line.